

Slika 10.1.1. Merenje aktivne snage i faktora snage metodom tri ampermetra.



Slika 10.1.1. Merenje aktivne snage i faktora snage metodom tri ampermetra.




Slika 10.1.1. Merenje aktivne snage i faktora snage metodom tri ampermetra.





Slika 10.1.1. Merenje aktivne snage i faktora snage metodom tri ampermetra.




Slika 10.1.1. Merenje aktivne snage i faktora snage metodom tri ampermetra.





Slika 10.1.1. Merenje aktivne snage i faktora snage metodom tri ampermeta.




Slika 10.1.1. Merenje aktivne snage i faktora snage metodom tri ampermetra.




Slika 10.1.1. Merenje aktivne snage i faktora snage metodom tri ampermeta.




Slika 10.1.1. Merenje aktivne snage i faktora snage metodom tri ampermetra.





Slika 10.1.1. Merenje aktivne snage i faktora snage metodom tri ampermetra.




Slika 10.1.1. Merenje aktivne snage i faktora snage metodom tri ampermeta.






Slika 10.1.1. Merenje aktivne snage i faktora snage metodom tri ampermetra.



Slika 10.1.1. Merenje aktivne snage i faktora snage metodom tri ampermeta.



$Z_p$	$I_1$	$I_0$	$I$	$P_m$	$P_t$	$\cos \varphi_m$	$\cos \varphi_t$	$\Delta P_{3A} / P_{3A}$	$\Delta \cos \varphi_{3A} / \cos \varphi_{3A}$
	mA	mA	mA	W	W			%	%
$L_1$	230	60	180						
$L_2$	280	60	230						
$C_1$	310	60	280						
$C_2$	210	60	160						

Tabela 10.1.1. Rezultati merenja aktivne snage i faktora snage metodom 3A.